

division of facilities construction and manag 4110 state office building, salt lake city, utah 84114 801,538,3018

richards bott architects 620 24th street ogden, utah 84401 801.394.3033

700 north

600 north

utah state university - emma eccles jones education building reroof
1600 old main hill, logan, utah 84302

700 north 550 north



property line
plastic laminate
plywood
resilient base
reinforce(d) (ing) solid core schedule specification square steel tempered glass typical vinyl composition tile temp gl

cever sheet / general information


building section reference

sheet reference

detail reference sheet reference

l elevation marker





elevation reference


sheet reference


wood framing (interrupted member)


700 north utah state university


existing
exterior
floor drain
foundation
fire extinguisher cab
finish(ed) floor
foot or feet
footing
furring

































## **general notes**

- A. Provide all miscellaneous flashing and accessories required for a complete job. Flash all roof penetrations. Remove and reinstall all miscellaneous
- B. All miscellaneous vents, flues, curbs, etc. to meet minimum code clearance above new roof line.
- C. Field verify exact sizes and dimensions.
- D. The existing roof was viewed with an infrared thermas imaging camera and no major areas of water were discovered. Therefore it was determined that the existing insulation is in good condition.
- E. Flash existing vir, flue, and window cleaning see 1/a2.1.

## keyed notes

- Disting single ply membrane to be removed, the existing fasteners may remain on existing polyisocyanurate insulation on a metal deck to remain, provide 1/4" Dens deck with new pvc single-ply membrane, mechanically
- 2 Remove existing metal parapet cap. Provide new prefinished. See 4/a2.1.
- 3 Mechanical penthouse or unit, remove and reinstall as required to flash existing curb, see 5/a2.1 sim.
- 4 Existing roof drain and over plan drain, remove and reinstall as required for new single-ply membrane, see 2/a2.1.
- 5 Remove existing reglet and provide new, see 3/a2.1.
- 6 Existing skylight to remain. Extend membrane under flashing. 7 Wrap existing beam with metal cap, similar to 4/a2.1
- 8 Flash existing scupper.
- Stisting cricket insulation to remain add additional 1/8" sloped insulation.

(10) Existing cricket to remain.

- 1) Flash around existing roof hatch, see 5/a1.2.
- 12 Expansion joint, see 6/a2.1.
- Remove existing eifs on existing metal studs, both sides. Provide (2) layers of 5/8" exterior gypsum board with 1/4" Dens-deck and single ply-membrane. Provide prefinished metal fastened at 8" o.c.
- Remove existing swamp cooler, flash curb and reinstall swamp cooler, see 5/a2.1.
- Extend membrane under existing flashing provide a metal flashing under existing. Recaulk existing flashing at window, see 8/a2.1
- Remove existing exhaust fan or equipment to flash existhing curb, reinstall equipment, see 5/a2.1.
- 17 Protect existing satellite to remain, flash pipe columns.
- 18 Provide wall mounted sign on interior wall next to door, see specifications.